



16	Screw M4X12	8		
15	battery bracket	1		
14	sealing ring	1		
13	water/gas valve	1		
12	screw M3X12	4		
11	plate	1		
10	flame detector	1		
9	O sealing ring	1		
8	ignition electrode	2		
7	burner (3 rows)	1		
6	thermal switch	1		
5	screw ST2.9/6	2		
4	MIG	11		
3	heat exchanger	1		
2	screw ST4.2X8	4		
1	chimney	1		
No.	Spare parts	Qty	No.	Spare parts Qty

JSD12 exploded drawing (Xiangji)